Instructions / Technical Data Sheet WO-WE W800 - Etching solution

Product description

W800 is used for surface preparation for the subsequent coating with <u>W700 - floor coating</u> or <u>W702 - 2K floor coating</u>. W800 removes stubborn dirt, oil-contaminated secretions and new concrete surfaces (lime), microfine roughened surface and improves the attachment (adhesion) of <u>W700</u> and <u>W702</u>.

Surface preparation

Before the treatment with W800 of the substrate must be stable, clean, dry and free of grease. To ensure this, prepare the surface with W810 - special cleaner.

Processing

Apply undiluted W800 evenly on the floor. (Use sprayer or watering can with shower head) and then spread evenly with a broom. Avoid treating more than 10 square meters at a time, to minimize harmful vapors. Let the W800 soak in for about 20 minutes and rinse thoroughly after use.

Storage and labeling according to Ordinance on Hazardous Substances / Self-assessment

About 24 months if properly stored between + 5°C to + 25°C in undamaged package. Keep away from heat, cold and moisture. Keep away from children, heat and open flames. Close properly the container when you don't work with it in order to avoid the hardening. Other data according to currently valid ordinances may be found in the safety data sheets and labels.

Safety instructions:

Keep out of the reach of children. Use only in well ventilated rooms. Wear protective clothing, protective gloves and face protection / safety goggles. Avoid skin and eye contact. Avoid inhalation of vapors. Rinse in contact with skin immediately with plenty of water. After eye contact immediately seek medical attention. Do not allow to enter drains. Follow the safety data sheet for more safety information.

Recommended additional products

W700 - Floor coating W702 - 2K Floor Coating W810 - Special Cleaner